

Inspection Photos


Location: Laramie Energy LLC My Way Ranch 16-15 Pad

Location ID: 334523

Date: 6/12/2024



Entrance to location - Photo #02472



Location - Photo #02478

Inspection Photos

Location: Laramie Energy LLC My Way Ranch 16-15 Pad

Location ID: 334523

Date: 6/12/2024



Well heads - Photo #02473



Separators - Photo #02475

Inspection Photos

Location: Laramie Energy LLC My Way Ranch 16-15 Pad

Location ID: 334523

Date: 6/12/2024



Meter run - Photo #02476



Tank battery - Photo #02477

Inspection Photos

Location: Laramie Energy LLC My Way Ranch 16-15 Pad

Location ID: 334523

Date: 6/12/2024



Open entry to wildlife - Photo #02483



Open entry to wildlife - Photo #02485

Inspection Photos

Location: Laramie Energy LLC My Way Ranch 16-15 Pad

Location ID: 334523

Date: 6/12/2024



Pig launcher - Photo #02486



Southwest corner of location - Photo #02489

Inspection Photos

Location: Laramie Energy LLC My Way Ranch 16-15 Pad

Location ID: 334523

Date: 6/12/2024



Northwest corner of location - Photo #02490