

Inspection Photos

API: 009-06117

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 6/13/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east at the location. There are areas where the crop has not re-established.



Inspection Photos



Photo 2. Facing southeast at the location. There are areas where the crop has not re-established.



Inspection Photos



Photo 3. Facing south at the location. There are areas where the crop has not re-established.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing east toward the surrounding crop which has a uniform crop cover..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources