

Inspection Photos

API: 009-06564

Operator: WEST TEXAS OPERATING
CO LLC DBA XTREME ENERGYCO

Inspection Date: 6/13/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing toward the wellsite. There is unused pipe laying next to the pumpjack that needs to be removed. The operator name on the sign is faded and needs to be updated.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06564 | Date: 6/13/2024

Inspection Photos



Photo 2. The chemical tank has no lid or labels but appears to be unused and needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources