

Inspection Photos
Location Name: State Antelope P-32 PAD
Location ID: 432677



Photo 1 – Gas Lift Injection Meter House and Methanol Tanks




Photo 2 – Container Label missing

Inspection Photos
Location Name: State Antelope P-32 PAD
Location ID: 432677



Photo 3 – Wells



Photo 4 – Production Equipment