

Inspection Photos
Location Name: R & R FARMS/21-31
Location #: 309789



Photo #1

R & R Farms 21-31 (123-25384) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 220 yds.



Photo #2

R & R Farms 21-31, 22-31D Battery site

Abandoned: ALL Equipment Removed

Plugged & Abandoned | PA (2-Wells)

