

Inspection Photos

API: 071-06260

Operator: MERIDIAN OIL INC

Inspection Date: 6/17/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the location. Perennial vegetation has re-established.



Inspection Photos



Photo 1. Facing south toward the location. Perennial vegetation has re-established.

