

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403728449

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: SCOUT ENERGY MANAGEMENT LLC	Operator No: 10779	Phone Numbers
Address: 13800 MONTFORT DRIVE SUITE 100		Phone: (970) 501-5157
City: DALLAS	State: TX	Zip: 75240
Contact Person: Chris Patterson	Email: chris.patterson@scoutep.com	Mobile: (970) 620-3456

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 24238 Initial Form 27 Document #: 403046027

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: WELL	Facility ID: _____	API #: 103-12563	County Name: RIO BLANCO
Facility Name: Equity AC McLaughlin Orphan 200		Latitude: 40.089180	Longitude: -108.873864
		** correct Lat/Long if needed: Latitude: _____	Longitude: _____
QtrQtr: NWNW	Sec: 5	Twp: 1N	Range: 102W
		Meridian: 6	Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications GM

Most Sensitive Adjacent Land Use Livestock
Grazing

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste
- ☐ Other E&P Waste
- ☐ Non-E&P Waste
- ☐ Produced Water
- ☐ Workover Fluids
- ☐ Oil
- ☐ Tank Bottoms
- ☐ Condensate
- ☐ Pigging Waste
- ☐ Drilling Fluids
- ☐ Rig Wash
- ☒ Drill Cuttings
- ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	SOILS	Unknown	Field Screening via PID and visual

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

In accordance with Rule 911.a, Scout is submitting this Form 27 to close the orphan well pad. Historically in this area Scout has occasionally encountered what appears to be historical drill cuttings remaining adjacent to the wells. Scout collected ten (10) soil samples from four (4) locations most likely to have been impacted at the orphan well pad as described in the attached Site Investigation Report dated June 17, 2024. All sample analytical results are below ECOM Table 915-1 RSSL cleanup concentrations and modified background soil concentrations. Supplemental Form 27 (document #403046027) included an approved reduced analyte suite for the decommissioning samples.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Please see Appendix C of attached Site Investigation Report. In June 2022, Scout acquired the Whiting assets in this area and took ownership of the orphan locations formerly owned and maintained by Whiting. As part of the transfer of operatorship process, Scout took ownership of the background soil sampling reports and analytical data from Whiting. Scout intends to apply the analytical data from the background soil sampling efforts to the orphan location closures to determine whether contaminants of concerns identified through future soil sampling are naturally occurring in the area, or are due to potentially historic impacts at the orphan locations.

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 10

Number of soil samples exceeding 915-1 7

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 100

NA / ND

-- Highest concentration of TPH (mg/kg) 1150.95

-- Highest concentration of SAR 17.6

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 4

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 915-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

Multiple discrete background grab samples were collected throughout the field to determine the naturally occurring background concentrations of EC, SAR, pH, and Arsenic. The resulting lab data indicated that EC ranged from 0.178 to 10.4 mmhos/cm, SAR was < 6, pH ranged from 7.71 to 9.04, and Arsenic ranged from 4.16 to 8.08 mg/kg. These ranges along with Table 915-1 were utilized to evaluate the onsite samples. Please see Appendix C of the attached Site Investigation Report for additional details on the background samples.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

If encountered the cuttings will be removed via a combination of mechanical and hand excavation in an effort to minimize disturbing the surrounding vegetation. The removed cuttings will be staged onsite.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

If encountered the cuttings (or any impacted material) will be staged and shredded onsite adjacent to the wells. The cuttings will then be processed through a soil shredder with a combination of soil and/or amendments at a ratio necessary to achieve Modified Table 915-1 Cleanup Concentrations.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

☐ Ex Situ

_____ Excavate and offsite disposal

_____ If Yes: Estimated Volume (Cubic Yards) _____

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Excavate and onsite remediation

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☐ Quarterly

☐ Semi-Annually

☐ Annually

☐ Other

☐ **Request Alternative Reporting Schedule:**

☐ Semi-Annually

☐ Annually

☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring

☐ Land Treatment Progress Report

☐ O&M Report

☐ Other

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator anticipates the remaining cost for this project to be: \$

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation?

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

If YES:

☒ Compliant with Rule 913.h.(1).

☒ Compliant with Rule 913.h.(2).

☒ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? Yes

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The location will be reclaimed to the present grade of the location or to the approximate original contour of the landscape and consistent with the 1000-series Rule. Seeding of the disturbed area will be performed in accordance with its intended use. The seed mix will be prescribed by the landowner. There are no known noxious weeds in the immediate area of the disturbance.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim ☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 10/16/2023

Proposed site investigation commencement. 06/21/2021

Proposed completion of site investigation. 08/08/2023

REMEDIAL ACTION DATES

Proposed start date of Remediation. 10/16/2023

Proposed date of completion of Remediation. 11/01/2023

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT	
1	10/10/2017
2	10/10/2017
3	10/10/2017
4	10/10/2017
5	10/10/2017
6	10/10/2017
7	10/10/2017
8	10/10/2017
9	10/10/2017
10	10/10/2017
11	10/10/2017
12	10/10/2017
13	10/10/2017
14	10/10/2017
15	10/10/2017
16	10/10/2017
17	10/10/2017
18	10/10/2017
19	10/10/2017
20	10/10/2017
21	10/10/2017
22	10/10/2017
23	10/10/2017
24	10/10/2017
25	10/10/2017
26	10/10/2017
27	10/10/2017
28	10/10/2017
29	10/10/2017
30	10/10/2017
31	10/10/2017
32	10/10/2017
33	10/10/2017
34	10/10/2017
35	10/10/2017
36	10/10/2017
37	10/10/2017
38	10/10/2017
39	10/10/2017
40	10/10/2017
41	10/10/2017
42	10/10/2017
43	10/10/2017
44	10/10/2017
45	10/10/2017
46	10/10/2017
47	10/10/2017
48	10/10/2017
49	10/10/2017
50	10/10/2017
51	10/10/2017
52	10/10/2017
53	10/10/2017
54	10/10/2017
55	10/10/2017
56	10/10/2017
57	10/10/2017
58	10/10/2017
59	10/10/2017
60	10/10/2017
61	10/10/2017
62	10/10/2017
63	10/10/2017
64	10/10/2017
65	10/10/2017
66	10/10/2017
67	10/10/2017
68	10/10/2017
69	10/10/2017
70	10/10/2017
71	10/10/2017
72	10/10/2017
73	10/10/2017
74	10/10/2017
75	10/10/2017
76	10/10/2017
77	10/10/2017
78	10/10/2017
79	10/10/2017
80	10/10/2017
81	10/10/2017
82	10/10/2017
83	10/10/2017
84	10/10/2017
85	10/10/2017
86	10/10/2017
87	10/10/2017
88	10/10/2017
89	10/10/2017
90	10/10/2017
91	10/10/2017
92	10/10/2017
93	10/10/2017
94	10/10/2017
95	10/10/2017
96	10/10/2017
97	10/10/2017
98	10/10/2017
99	10/10/2017
100	10/10/2017

Additional information regarding this site assessment can be found in the attached Site Investigation Report dated June 17, 2024.

Ten (10) soil samples were collected from the former wellhead, area of concern, and tailings piles at Equity AC McLaughlin Orphan 200 Pad on 8/22/2022, 11/1/2022, 06/29/2023, 8/1/2023 and 11/15/2023 and analyzed for ECMC Table 915-1 contaminants of concern. The locations of the former wellhead, area of concern, and tailings pile are shown on Figure 2.

Results from the discrete soil samples collected from the AOC, tailings pile, and wellhead on August 22, 2022, November 1, 2022, June 29, 2023, and August 1, 2023, exhibited either SAR or TPH exceedances greater than ECMC Table 915-1 RSSLs and background levels. To address these exceedances, Scout processed the tailings piles through a soil shredder with a combination of soil and/or amendments at a ratio necessary to achieve ECMC Table 915-1 Cleanup Concentrations. Kleinfelder collected additional discrete soil samples from the AOC, tailings pile, and wellhead on August 1, 2023, and November 15, 2023. Both SAR and TPH were detected at concentrations below the ECMC Table 915-1 cleanup concentrations in these subsequent samples.

Site soil conditions and soil sample laboratory analytical results are provided in Table 1 and Table 2. Based on the results of the assessment of the soil conditions at the AOC, wellhead, and tailings pile, the location does not demonstrate any exceedances for ECMC Table 915-1. Therefore, Scout requests approval for No Further Action (NFA) associated with the Equity AC McLaughlin Orphan 200 Pad.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Chris Patterson

Title: Sr. HSE Coordinator

Submit Date:

Email: chris.patterson@scoutep.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved:

Date:

Remediation Project Number: 24238

COA Type

Description

0 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

403827382	SITE INVESTIGATION REPORT
-----------	---------------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)