

Inspection Photos

06/14/2024

Operator: ANSCHUTZ EXPLORATION CORP
#3104

Location ID: 484545

Inspection Doc: 696205876

Moffat County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 484545



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provides an overview of the Location from south, southwest, northeast to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 484545



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 484545



Photo 3: Signage at Location entrance. Well signage/information posted. Information per rule 605.a.(1) and 605.a.(2) not posted.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 484545



Photo 4: Pipe equipment covered/taped to prevent wildlife access.

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 484545



Photo 5: Topsoil stockpile.

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 484545



Photo 6: Photos examples showing the slope drains installed on the southwest and northwest ends of the Location.

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 484545



Photo 6: Erosion blankets implemented along portions of the fill slope.