

# Inspection Photos

06/14/2024

**Operator:** ANSCHUTZ EXPLORATION CORP  
#3104

**Location ID:** 315979

**Inspection Doc:** 696205883

Rio Blanco County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 315979



**Photo 1:** Photo shows soil stockpile on the south end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 315979



**Photo 2:** Continued from photo 1. Photo shows Halogeton establishment/germination on the stockpiles. Weed management efforts have not been performed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 315979



**Photo 3:** See comments under photo 2.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 315979



**Photo 4:** Continued from previous photos. Photo shows Bulbous Bluegrass establishment on the soil stockpiles of the Location. Plants have matured and seeded out.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources