

Inspection Photos
Location Name: Dinner 1-1-19
Location ID: 302337



Photo 1: Wellhead Sign



Photo 2: Wellhead; overgrown vegetation