

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403828532

Date Received:  
06/19/2024

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

10 of 10 CAs from the FIR responded to on this Form

10 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 7125  
Name of Operator: BEEMAN OIL & GAS INC  
Address: 13635 E 104TH AVENUE STE 400  
City: COMMERCE CITY State: CO Zip: 80022

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Galloway, Kelly</u>	<u>(970) 210-2896</u>	<u>kgalloway.werc@gmail.com</u>
<u>Lawton, Lisa</u>	<u>(970) 846-4639</u>	<u>lisa@beemanoil.com</u>
<u>Pate, James</u>	<u>(720) 377-3366</u>	<u>jspconcrete@yahoo.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 715500173  
Inspection Date: 06/06/2024 FIR Submit Date: 06/06/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BEEMAN OIL & GAS INC Company Number: 7125  
Address: 13635 E 104TH AVENUE STE 400  
City: COMMERCE CITY State: CO Zip: 80022

LOCATION - Location ID: 423933

Location Name: Stoddard Number: 33-30 County: MOFFAT  
Qtrqtr: NWSE Sec: 30 Twp: 6N Range: 90W Meridian: 6  
Latitude: 40.447208 Longitude: -107.531269

FACILITY - API Number: 05-081-00 Facility ID: 423935

Facility Name: Stoddard Number: 33-30  
Qtrqtr: NWSE Sec: 30 Twp: 6N Range: 90W Meridian: 6  
Latitude: 40.447208 Longitude: -107.531269

CORRECTIVE ACTIONS:

1  CA# 195705

Corrective Action: All load lines or tank valves that can be used as a load line will be capped or plugged. Date: 06/12/2024

Response: CA COMPLETED Date of Completion: 06/12/2024

Operator Comment: Replaced cap

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

**2**  CA# 195706

Corrective Action: Remove and properly dispose of oily waste and impacted soil.

Date: 06/22/2024

Response: CA COMPLETED

Date of Completion: 06/18/2024

Operator  
Comment:

Removed soil and waste. Will dispose of in a proper manner when the load test results come back

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

**3**  CA# 195707

Corrective Action: Remove and properly dispose of oily waste and impacted soil.

Date: 06/22/2024

Response: CA COMPLETED

Date of Completion: 06/18/2024

Operator  
Comment:

Removed soil and waste. It will be properly disposed of when test results come back

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

**4**  CA# 195708

Corrective Action: Remove and properly dispose of oily waste and impacted soil.

Date: 06/22/2024

Response: CA COMPLETED

Date of Completion: 06/18/2024

Operator  
Comment:

Removed waste and soil. Will be properly disposed when test results come back

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

**5**  CA# 195709

Corrective Action: Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled in accordance with the U.S. Department of Transportation's Hazardous Materials Regulations, will retain the markings, placards, and labels on the Container. Such markings, placards, and labels will be retained on the Container until it is sufficiently cleaned of residue and purged of vapors to remove any potential hazards.

Date: 06/17/2024

Response: CA COMPLETED

Date of Completion: 06/14/2024

Operator  
Comment:

New placard was installed

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

6  CA# 195710

Corrective Action: Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.

Date: 06/22/2024

Response: CA COMPLETED

Date of Completion: 06/13/2024

Operator Comment: We have set up an appointment for Mountain West Energy Services to calibrate all of our meters. They are a couple weeks out

ECMC Decision: Approved pending re-inspection

ECMC Representative:

7  CA# 195711

Corrective Action: Install wildlife protection equipment.

Date: 06/17/2024

Response: CA COMPLETED

Date of Completion: 06/18/2024

Operator Comment: added wildlife protection material

ECMC Decision: Approved pending re-inspection

ECMC Representative:

8  CA# 195712

Corrective Action: All equipment not hooked up or out of service will be removed from location.

Date: 06/22/2024

Response: CA COMPLETED

Date of Completion: 06/17/2024

Operator Comment: Equipment was hooked back up to use

ECMC Decision: Approved pending re-inspection

ECMC Representative:

9  CA# 195713

Corrective Action: All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.

Date: 06/14/2024

Response: CA COMPLETED

Date of Completion: 06/14/2024

Operator Comment: all rubbish, supplies, trash and debris have been cleaned up.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

10  CA# 195714

Corrective Action: Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.

Date: 06/22/2024

Response: CA COMPLETED

Date of Completion: 06/18/2024

Operator Comment: all debris has been cleaned in area

ECMC Decision: Approved pending re-inspection

ECMC Representative: This was missing a vent cap.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lisa Lawton

Signed: \_\_\_\_\_

Title: Agent

Date: 6/19/2024 1:44:29 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403828532	FIR RESOLUTION SUBMITTED
403828565	Tank label and hook up, new cap on vent with debris removed
403829985	Cleaned location
403829987	cap on pipe
403829989	cleaned soil and location
403829991	placard
403829992	wildlife protection

Total Attach: 7 Files