

Inspection Photos
Location Name: Antelope G-29 PAD
Location ID: 422161



Photo 1 – Tank Battery




Photo 2 – Tank Battery Signs

Inspection Photos
Location Name: Antelope G-29 PAD
Location ID: 422161



Photo 3 – Separators – Tumbleweeds



**Photo 4 – Separators – Open to Atmosphere and
Unmarked Riser**

Inspection Photos
Location Name: Antelope G-29 PAD
Location ID: 422161




Photo 5 – Risers Unmarked



Photo 6 – Wellhead – Tumbleweeds

Inspection Photos
Location Name: Antelope G-29 PAD
Location ID: 422161



Photo 7 – Wellhead – Tumbleweeds



Photo 8 – Wellhead – Tumbleweeds and Unmarked Risers

Inspection Photos
Location Name: Antelope G-29 PAD
Location ID: 422161



Photo 9 – Wellheads



Photo 10 – Compressor Area