

Inspection Photos  
Location Name: Antelope I-29 PAD  
Location ID: 422173



Photo 1 – Wellhead – Unmarked Risers

Photo 2 – Wellhead – Sign faded; no longer visible

Inspection Photos  
Location Name: Antelope I-29 PAD  
Location ID: 422173



Energy and Carbon Management Commission  
40.36763, -104.3514, 4544.5ft  
06/12/2024 13:17:01



Energy and Carbon Management Commission  
40.3675, -104.3513, 4541.9ft  
06/12/2024 13:17:16

**Photo 3 – Wellhead – Sign faded; no longer visible**

**Photo 4 – Wellhead**

Inspection Photos  
Location Name: Antelope I-29 PAD  
Location ID: 422173



Energy and Carbon Management Commission  
40.3675, -104.3513, 4537.4ft  
06/12/2024 13:17:19





Energy and Carbon Management Commission  
40.36737, -104.35124, 4539.0ft  
06/12/2024 13:17:45

Photo 5 – Wellhead – Sign faded; no longer visible

Photo 6 – Wellheads

Inspection Photos  
Location Name: Antelope I-29 PAD  
Location ID: 422173



**Photo 7 – Wellhead – Sign faded; no longer visible**

**Photo 8 – Wellhead – Sign faded; no longer visible**

**Inspection Photos**  
**Location Name: Antelope I-29 PAD**  
**Location ID: 422173**



Energy and Carbon Management Commission  
40.36748, -104.35167, 4539.4ft  
06/12/2024 13:18:21



Energy and Carbon Management Commission  
40.3679, -104.3519, 4538.1ft  
06/12/2024 13:18:39

**Photo 9 – N-29 Wellhead Site**

**Photo 10 – Separators**

**Inspection Photos**  
**Location Name: Antelope I-29 PAD**  
**Location ID: 422173**



**Photo 11 – Tank Battery**