

Inspection Photos
Location Name: Antelope 14-21 PAD
Location ID: 441376



Photo 1 – Separators – Unmarked Risers in varies spots



Photo 2 – Gas Lift Injection Meter House

Inspection Photos
Location Name: Antelope 14-21 PAD
Location ID: 441376



Photo 3 – Wellheads



**Photo 4 – E14-21-16XRLNC Wellhead Site –
Unmarked Risers**