

# Inspection Photos

API: 071-08228

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 6/18/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast toward the access road. There are undesirable weeds along the road that need to be controlled.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** Facing northeast toward the wellsite. There are undesirable weeds throughout the location that need to be controlled.





## Inspection Photos



**Photo 3.** Facing toward the well. There are weeds (Kochia) growing around the equipment which will be a fire hazard.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:071-08228 | Date: 6/18/2024