



Inspection Photos
Location Name: Knowlton 15
Location ID: 081-05649
Remediation Project# 34336
Inspection Date: 6/17/2024

This marker appears to identify a rig anchor that is in the ground. The anchor is a cable.
Note; The subpanel at the left of photo. Corrective Action:

Jun 17, 2024 12:42:04 PM



Inspection Photos

Location Name: Knowlton 15

Location ID: 081-05649

Remediation Project# 34336

Inspection Date: 6/17/2024

The tee post at left of photo was assumed to be a marker indicating the PA wellhead. Wiring can be seen coming from the ground. Corrective Action: remove all equipment from the location, including wiring, markers, rig anchors, electrical infrastructure, etc.

Jun 17, 2024 12:52:02 PM

40 3344886098057N 107 60736635886133W





Inspection Photos

Location Name: Knowlton 15

Location ID: 081-05649

Remediation Project# 34336

Inspection Date: 6/17/2024

The tee post was assumed to be a marker indicating the PA wellhead. Wiring can be seen coming from the ground. Corrective Action: remove all equipment from the location, including wiring, markers, rig anchors, electrical infrastructure, etc.

