

Inspection Photos

Location Name: GovPohlman 2

Location ID: 081-05172

Remediation Project #: 10638

Inspection Date: 6/17/2024

Well was SI at time of inspection. Note sandstone in foreground of photo. Sandstone was observed daylighting in a few places on pad.

Jun 17, 2024 12:11:28 PM
40.327034373767674N 107.60310818441212W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: GovPohlman 2

Location ID: 081-05172

Remediation Project #: 10638

Inspection Date: 6/17/2024

Area of pad between camera and electric pole is where there was a land treatment project. This area is being resampled as a part of project 10638. No observable hydrocarbon was witnessed.

Jun 17, 2024 12:11:31 PM
40.327052562497556N 107.60309938341379W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: GovPohlman 2

Location ID: 081-05172

Remediation Project #: 10638

Inspection Date: 6/17/2024

Sandstone

Jun 17, 2024 12:13:00 PM
40.327039319090545N 107.60297709144652W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Jun 17, 2024 12:13:09 PM
40.327074732631445N 107.60309787467122W

Inspection Photos

Location Name: GovPohlman 2

Location ID: 081-05172

Remediation Project #: 10638

Inspection Date: 6/17/2024

Treatment area and some daylighted sandstone on pad. The sand stone appears to not be continuous at surface of pad.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources