



Jun 17, 2024 1:25:29 PM
40.32370860222727N 107.6118562091142W

Inspection Photos
Location Name: Foster State
Location ID: 081-07821
Remediation Project: 35750
Inspection Date: 6/17/2024

Foster State well pad as
seen from the Deer
Creek 1pad.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Foster State
Location ID: 081-07821
Remediation Project: 35750
Inspection Date: 6/17/2024


Foster State well pad as
seen from the Deer
Creek 1pad.



Jun 17, 2024 1:25:33 PM
40.323708560317755N 107.61185612529516W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Foster State
Location ID: 081-07821
Remediation Project: 35750
Inspection Date: 6/17/2024

Sign at entry to location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Foster State
Location ID: 081-07821
Remediation Project: 35750
Inspection Date: 6/17/2024

Looking North. There was a buried liner and soil piled on top. It is believed this is a former cuttings area. Soil stored inside this bermed/lined area should be sampled for TABLE 915-1. The liner MUST be removed and not buried





Inspection Photos
Location Name: Foster State
Location ID: 081-07821
Remediation Project: 35750
Inspection Date: 6/17/2024

Photo shows north west
side of pad where
lined/bermed area is.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Jun 17, 2024 1:35:01 PM
40.32196084968746N 107.61331315152347W

Inspection Photos
Location Name: Foster State
Location ID: 081-07821
Remediation Project: 35750
Inspection Date: 6/17/2024

Photo shows soil piled. It is believed this is a former cuttings storage area. Soil stored inside this bermed/lined area should be sampled for Table 915-1. The liner **MUST** be removed and not buried



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Foster State
Location ID: 081-07821
Remediation Project: 35750
Inspection Date: 6/17/2024

Photo shows what is believed this is a former cuttings area. Soil stored inside this bermed/lined area should be sampled for Table 915-1. The liner MUST be removed and not buried



Jun 17, 2024 1:35:11 PM
40.32202580943704N 107.61331818066537W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Foster State
Location ID: 081-07821
Remediation Project: 35750
Inspection Date: 6/17/2024

Sign on ground near what is believed to be the Wellhead, the exact location of the PA wellhead was obvious.

Jun 17, 2024 1:35:26 PM
40.322117884643376N 107.61332421563566W





Inspection Photos
Location Name: Foster State
Location ID: 081-07821
Remediation Project: 35750
Inspection Date: 6/17/2024

Looking east. Note: stored soil, paneling on ground, stock tanks on pad.

Jun 17, 2024 1:36:19 PM
40.32215606421232N 107.613430833444W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Jun 17, 2024 1:36:21 PM
40.32215585466474N 107.6134305819869W

Inspection Photos
Location Name: Foster State
Location ID: 081-07821
Remediation Project: 35750
Inspection Date: 6/17/2024

Photo shows lined soil storage area. Liner must be removed, soil stored in liner shall be sampled for Table 915-1. Livestock supplies on pad.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources