

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2024

Submitted Date:

06/20/2024

Document Number:

694500669

FIELD INSPECTION FORMLoc ID 450386 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		htrujillo@rlbayless.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442692	TANK BATTERY	AC	08/04/2015		-	Moffat Tank Battery 442692	EI

General Comment:

Environmental staff, Kris Neidel inspected the tank battery. It is not know if combustor adjacent to location is related to this tank battery, the combustor was burning gas. . Any corrective action(s) from previous inspections that have not been addressed are still applicable See attached See attached Photos.

