

Inspection Photos

06/19/2024

Operator: UTAH GAS OP LTD DBA UTAH GAS
CORP - 10539

Location ID: 315645

Inspection Doc: 696205899

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315645



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315645



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315645




Photo 3: Wellhead. Tank battery signage posted at shed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315645



Photo 4: Produced water tank at battery facility. Capacity information not observed on tank. Photo right shows liner at battery in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315645




Photo 5: Photo taken from the south end of the Location. Photo shows unmarked anchor.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources