

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

01/10/2024

Document Number:

403649697

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

**Operator Information**

ECMC Operator Number: 47120 Contact Person: Erik Mickelson  
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306  
Address: P O BOX 173779 Fax: ( )  
City: DENVER State: CO Zip: 80217-3779 Email: Erik\_Mickelson@oxy.com

**Identification Information**

API Number: 05 - - ECMC Facility ID: 485209 Initial Form 19 or 27 Document number:  
Facility Name: LIZZY Facility Number: 8-36HZ Facility Type: LOCATION  
Location QtrQtr: SENE Section: 36 Township: 1N Range: 68W Meridian: 6  
County: WELD Field Name:  
Federal, Indian or State Lease Number:

## Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional  
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

## Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 772180 Facility Name: Lhotak 141966 Facility Type: background  
Location: QtrQtr: NWNW Sec: 1 Twp: 1S Range: 68W Meridian: 6  
County Name: ADAMS Latitude: 39.999310 Longitude: -104.954802

**Sample Information:**

The following Sample Information has been reviewed by the ECMC:

Batch ID: 115922 Document Name: Size of file in bytes: 79360 File Name: 2023\_10\_24\_Lhotak 141966 SGS ECMC.xls  
SampleType: Matrix:  
Facility ID: 772180 Sample ID: 655174 Sample Name: Lhotak 141966 Sample Date: 10/24/2023  
Collection Point: Dom Matrix: WATER Pre Post: Voluntary baseline sample  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: Accutest Lab Sample ID: DA59564-1

Batch ID: 115925		Document Name: Size of file in bytes: 35840		File Name: 2023_10_24_Lhotak_141966 Isotech NG4 ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772180	Sample ID: 655178	Sample Name: Lhotak 141966		Sample Date: 10/24/2023	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 896566		

  

Batch ID: 115924		Document Name: Size of file in bytes: 31232		File Name: 2023_10_24_Lhotak 141966 Trip Blank SGS ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772180	Sample ID: 655176	Sample Name: Lhotak 141966		Sample Date: 10/24/2023	
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59581-1		

  

Batch ID: 115925		Document Name: Size of file in bytes: 35840		File Name: 2023_10_24_Lhotak_141966 Isotech NG4 ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772180	Sample ID: 655177	Sample Name: Lhotak 141966		Sample Date: 10/24/2023	
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 896566		

  

Batch ID: 115923		Document Name: Size of file in bytes: 25600		File Name: 2023_10_24_Lhotak 141966 SGS DRO ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772180	Sample ID: 655175	Sample Name: Lhotak 141966		Sample Date: 10/24/2023	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59564-1		

#### Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
772180	403649710	2023_10_24_Lhotak_141966_Spigot.jpg	Photographs	JPG
772180	403649712	2023_10_24_Lhotak_141966_Wellhead.jpg	Photographs	JPG
772180	403649702	2023_10_24_Lhotak 141966 SGS.pdf	Analytical Laboratory Report	PDF
772180	403649698	2023_10_24_Lhotak_141966 Isotech NG4.pdf	Analytical Laboratory Report	PDF
772180	403649707	2023_10_24_Lhotak_141966_FS_ECMC.pdf	Field Data Report	PDF
772180	403649700	2023_10_24_Lhotak 141966 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
772180	403649709	2023_10_24_Lhotak_141966_Pre Post Purge.jpg	Photographs	JPG
772180	403649711	2023_10_24_Lhotak_141966_Wellhead Spigot Location.jpg	Photographs	JPG

#### Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

## General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	06/20/2024
Total: 1 comment(s)		