

Final Reclamation and Stormwater Inspection

Date: 06/18/2024

Operator: MCCARTNEY ENGINEERING LLC - 55030

Location ID: 320429

Inspection Document #: 708201337

Adams County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: HSR-Fulenwider 12-10
Location ID: 320429



Photo 1. The subsidence previously documented appears to have been filled with soil and leveled. The location and adjacent field also appear to have been recently planted. A follow-up inspection will be conducted at a later date to verify crop establishment.

Inspection Photos
Location Name: HSR-Fulenwider 12-10
Location ID: 320429



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: HSR-Fulenwider 12-10
Location ID: 320429



Photo 3. Facing south; see comments in Photo 1.

Inspection Photos
Location Name: HSR-Fulenwider 12-10
Location ID: 320429



Photo 4. Facing west; see comments in Photo 1.