

Final Reclamation and Stormwater Inspection

Date: 06/18/2024

Operator: MCCARTNEY ENGINEERING LLC - 55030

Location ID: 320422

Inspection Document #: 708201338

Adams County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: HSR Fulenwider 4-10
Location ID: 320422



Photo 1. Facing south at the start of the access road. Erosion degradation appears to have been repaired.

Inspection Photos
Location Name: HSR Fulenwider 4-10
Location ID: 320422



Photo 2. Facing south towards the former well location; see comments in Photo 1.

Inspection Photos
Location Name: HSR Fulenwider 4-10
Location ID: 320422



Photo 3. Facing north along the access road; see comments in Photo 1.

Inspection Photos
Location Name: HSR Fulenwider 4-10
Location ID: 320422



Photo 4. Facing north near the former location. Weed debris and undesirable vegetation appears to have been removed. The location and adjacent field appears to have been recently planted, a follow-up inspection will be performed at a later date to verify vegetation/crop establishment.

Inspection Photos
Location Name: HSR Fulenwider 4-10
Location ID: 320422



Photo 5. Facing north near the former tank battery; see comments in Photo 4.

Inspection Photos
Location Name: HSR Fulenwider 4-10
Location ID: 320422



Photo 6. Facing southwest near the former tank battery; see comments in Photo 4.

Inspection Photos
Location Name: HSR Fulenwider 4-10
Location ID: 320422



Photo 7. Facing south near the former well location; see comments in Photo 4.