

Inspection Photos

June 12th, 2024

Operator: BMG Drilling Corporation - 7650

Location ID: 325319

Inspection Document #: 714000846

La Plata County, CO

Township: SWNW 4 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Jacques 1
Location ID: 325319



Photo 1. View of the project area taken from the western edge facing center.



Inspection Photos
Location Name: Jacques 1
Location ID: 325319



Photo 2. View of recent reclamation work where area was drill seeded and mowed.

Inspection Photos
Location Name: Jacques 1
Location ID: 325319



Photo 3. View of jointed goatgrass, a Colorado List B noxious weed observed in the western portion of the disturbance.