

Inspection Photos

June 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306761

Inspection Document #: 714000851

La Plata County, CO

Township: NWNE 11 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Presentation Medina A 2

Location ID: 306761



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Presentation Medina A 2
Location ID: 306761



Photo 2. Impacted surface material corrective action identified in the previous inspection doc #714000499 has been addressed/resolved.

Inspection Photos

Location Name: Presentation Medina A 2

Location ID: 306761



Photo 3. Storm water corrective action identified in the previous inspection doc #714000499 has been addressed/resolved.

Inspection Photos
Location Name: Presentation Medina A 2
Location ID: 306761



Photo 4. Unused oil and gas equipment corrective action identified in the previous inspection doc #714000499 has been addressed/resolved.