

Inspection Photos
Location Name: Peoria J Sand unit 36
Location ID: 320628



Pic 1 tanks



Pic 2 Separator

Inspection Photos
Location Name: Peoria J Sand unit 36
Location ID: 320628

Jun 18, 2024 at 9:59:12 AM
39.660872,-104.115428
Wapahoe County
ECMC



Pic 3 Pit

Jun 18, 2024 at 10:06:50 AM
39.661723,-104.104795
Wapahoe County
ECMC



Pic 4 Pump jack / wellhead

Inspection Photos
Location Name: Peoria J Sand unit 36
Location ID: 320628



Pic 5 Stained soil around wellhead / mechanical issue