

Inspection Photos

API: 071-09659

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 6/21/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the wellsite.



Inspection Photos



Photo 2. Facing east along the fill slope that is stabilized with perennial vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing toward production pit. The fence needs maintenance around the pit.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-09659 | Date: 6/21/2024

Inspection Photos



Photo 4. There are wood pallets that should be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. There is a dripping leak at the wellhead that needs to be fixed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. The engine skid has been cleaned up.

