

# Inspection Photos

API: 071-09251

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 6/21/2024

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing southeast toward the access road.



## Inspection Photos



**Photo 2.** Facing northwest toward the wellsite..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-09251 | Date: 6/21/2024

Inspection Photos



**Photo 3.** Facing toward the well which is temporarily abandoned..



## Inspection Photos



**Photo 4.** Facing southwest at the location. The vegetation is well established in the interim area..

