

Inspection Photos

06/19/2024

Operator: UTAH GAS OP LTD DBA UTAH GAS
CORP - 10539

Location ID: 315469

Inspection Doc: 696205923

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315469



Photo 1: Photos 1-2 taken from the Location entrance on the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315469



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315469



Photo 3: Culvert remaining at the Location entrance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315469



Photo 4: Photos 4-7 examples showing the vegetation throughout the reclamation; vegetation observed are predominantly Undesirable and Noxious Plant Species including Bull thistle, Houndstongue and Common Mullein.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315469



Photo 5: See comments under photo 4. Vegetation in photo predominantly Bull thistle and Houndstongue.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315469



Photo 6: See comments under photo 4. Vegetation in photo predominantly Bull thistle and Common Mullein.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315469



Photo 7: See comments under photo 4. Vegetation in photo predominantly Houndstongue.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources