

Inspection Photos

API: 071-09472

Operator: OGRIS OPERATING LLC

Inspection Date: 6/20/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. There is a water discharge point at the beginning of the access road in the canyon. The fence is in disrepair and needs to be removed or repaired..



Inspection Photos



Photo 2. Facing west toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09472 | Date: 6/20/2024

Inspection Photos



Photo 3. There is still oily fluid in the engine skid and stained soils.

