

# Inspection Photos

API: 071-09535

Operator: OGRIS OPERATING LLC

Inspection Date: 6/20/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** There is a water discharge point at the beginning of the access road in the canyon. The fence is in disrepair and needs to be removed or repaired.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-09535 | Date: 6/20/2024



## Inspection Photos



**Photo 2.** Facing northwest toward the wellsite.





## Inspection Photos



**Photo 3.** Facing south along the fill slope which is stabilized with vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:071-09535 | Date: 6/20/2024