

# Inspection Photos

API: 071-09536

Operator: OGRIS OPERATING LLC

Inspection Date: 6/20/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east toward the wellsite.





## Inspection Photos



**Photo 2.** There was a release of fluids next to the meter shed..





## Inspection Photos



**Photo 3.** The pit is adequately fenced.

