

Inspection Photos

Operator: CAERUS PICEANCE LLC – 10456

Location Name: PICEANCE CREEK UNIT #T58X-8G

Location ID: 316245 API #: 05-103-10098

Inspection Date: 6/19/2024 Inspection Doc#: 693807374



Location overview looking SE entrance with sign



Injection Wellhead plugged and abandoned