

Inspection Photos

Operator: CAERUS PICEANCE LLC – 10456

Location Name: PICEANCE CREEK UNIT #F13-8G

Location ID: 314860 API #: 05-103-07435

Inspection Date: 6/19/2024 Inspection Doc#: 693807383



06.19.2024 10:42

Location overview looking SE entrance with sign



06.19.2024 10:42

Injection Wellhead inside housing