

Inspection Photos

Operator: CAERUS PICEANCE LLC – 10456

Location Name: PICEANCE CREEK UNIT #T73-7G

Location ID: 315151 API #: 05-103-07993

Inspection Date: 6/19/2024 Inspection Doc#: 693807385



Location overview looking N entrance with sign



Injection Wellhead inside housing