

Inspection Photos

Operator: CAERUS PICEANCE LLC – 10456

Location Name: PICEANCE CREEK UNIT #T55X-7G

Location ID: 316244 API #: 05-103-10097

Inspection Date: 6/19/2024 Inspection Doc#: 693807387



Location overview looking SE entrance with sign



Injection Wellhead inside housing

