

Inspection Photos

Operator: CAERUS PICEANCE LLC – 10456


Location Name: PICEANCE CREEK UNIT #T26-7G

Location ID: 314731 API #: 05-103-07091

Inspection Date: 6/19/2024 Inspection Doc#: 693807389



Location overview looking SW entrance with sign



Injection Wellhead inside housing

