

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 996 From entrance to location

Photo # 997 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 998 Location



Photo # 999 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Jun 21, 2024 at 1:10:31 PM
CO



Jun 21, 2024 at 1:11:20 PM
CO

Photo # 1000 Location

Photo # 1001 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 1002 Wellhead sign weathered/faded & starting to become illegible



Photo # 9283 From inspection 708903254 conducted on 03/11/2024 - Unused equipment/ECD disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 7333 From inspection 708903830 conducted on 05/16/2024 Unused equipment/ECD disconnected



Photo # 1003 Unused equipment/ECD disconnected