

Operator: BCEI

Location Name: State Antelope 11-14-1HZ

Loc ID: 420123

Inspection: 696306413



Exhibit A



Exhibit B

CA: 144WT Tank - NFPA and Capacity Labels are peeling away North 300 BBL Water Tank Labels - Capacity Label has peeled away; no longer visible.
Install sign to comply with Rule 605.h.

CA Resolution: Operator has reported that new NFPA and Capacity labels have been installed on the identified tanks to comply with Rule 605.h.