

Operator: BCEI

Location Name: State Antelope 14-2

Loc ID: 435952

Inspection: 696306415



Exhibit A

CA: Southeast Oil Tanks missing NFPA Labels. See photos. Install sign to comply with Rule 605.h.

CA Resolution: Operator has reported that new NFPA and Capacity labels have been installed on the identified tanks to comply with Rule 605.h.