

Inspection Photos
Location Name: HV Ranch 32-1
API Number: 115-06062



1. Lease sign at wellhead.



2. View of wellhead.

Inspection Photos
Location Name: HV Ranch 32-1
API Number: 115-06062



3. Tubing pressure at time of inspection.



4. Casing pressure at time of inspection.

Inspection Photos
Location Name: HV Ranch 32-1
API Number: 115-06062



5. Well site overview.



6. View of tank battery.

Inspection Photos
Location Name: HV Ranch 32-1
API Number: 115-06062



7. Debris pile inside location fencing.



8. Location overview.