

Inspection Photos
Location Name: ERICKSON-66N64W/5SWSE
Location #: 330150



Photo #1
Erickson 5-43 (123-18513) Wellsite
Producing | PR
prior photo



Photo #2
Erickson A 8-1, A 8-17,
Erickson 5-43 Battery site
Inactive | Shut-down
Equipment documented: Loc. # 306018
Formerly served:
Erickson A 8-2, A 8-7, A 8-8 ;
Plugged & Abandoned | PA prior photo

Inspection Photos
Location Name: ERICKSON-66N64W/5SWSE
Location #: 330150



Photo #3
Erickson 5-43 Wellsite
Temporarily Abandoned | TA
Incident: WH strike; 2024-06-14



Photo #4
Erickson 5-43 Wellsite
Temporarily Abandoned | TA
Incident: WH strike; 2024-06-14

Inspection Photos

Location Name: ERICKSON-66N64W/5SWSE

Location #: 330150

| Associated Well(s) | API | Status |
|--------------------|-----------|--------|
| 1. Erickson A 8-1 | 123-23826 | SI |
| 2. Erickson A 8-17 | 123-23751 | SI |
| 3. Erickson 5-43 | 123-18513 | TA |

Photo #5

Erickson A 8-1, A 8-17,
Erickson 5-43 Battery site

Inactive | Shut-down

Associated Well(s): 3

1: Temporarily Abandoned | TA; 2: Shut-In | SI