

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/32SWSE

Location ID: 324459

Date: 6/20/2024



Entrance to location - Photo #02743



Location - Photo #02744

Date: 6/20/2024



Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/32SWSE

Location ID: 324459

Date: 6/20/2024



Meter run - Photo #02752



Tank battery - Photo #02753

Inspection Photos
Location: Gunnison Energy LLC Federal -610S90W/32SWSE
Location ID: 324459
Date: 6/20/2024



No access to bradenhead valve - Photo #02748



No access to bradenhead valve - Photo #02749

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/32SWSE

Location ID: 324459

Date: 6/20/2024



Southeast corner of location - Photo #02760



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources