

# Inspection Photos

June 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 320867

Inspection Document #: 714000866

Archuleta County, CO

Township: SESW 2 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Location Name: Kerrigan 32-6-1, 3  
Location ID: 320867

6/18/24  
+37.046069,-107.484565  
335° NW



Photo 1. View of the well disturbance from the access point facing center.



Inspection Photos  
Location Name: Kerrigan 32-6-1, 3  
Location ID: 320867



**Photo 2.** View of the western interim reclamation area facing north. Vegetation comprised predominantly of smooth brome.





Inspection Photos  
Location Name: Kerrigan 32-6-1, 3  
Location ID: 320867

