

Inspection Photos

June 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306839

Inspection Document #: 714000867

La Plata County, CO

Township: SWNE 10 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Brown 32-6-10 2
Location ID: 306839



Photo 1. View of the well disturbance taken from the access road facing center.

Inspection Photos
Location Name: Brown 32-6-10 2
Location ID: 306839



Photo 2. View of the eastern interim reclamation area facing south.

Inspection Photos
Location Name: Brown 32-6-10 2
Location ID: 306839



Photo 3. View of large patches of russian knapweed (A Colorado List B Noxious Weed) Observed in the eastern fill slope/interim reclamation area.

6/18/24
+37.035184,-107.485012
314° NW

