

# Inspection Photos

June 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326188

Inspection Document #: 714000869

La Plata County, CO

Township: NWSW 3 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Brown 32-6-03 1  
Location ID: 326188

6/18/24  
+37.044440,-107.492183  
1° N



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 1.** View of the well disturbance taken from the access point facing center.

API #: 067-07620



Inspection Photos  
Location Name: Brown 32-6-03 1  
Location ID: 326188



**Photo 2.** View of damaged location sign that needs repair.



Inspection Photos  
Location Name: Brown 32-6-03 1  
Location ID: 326188



**Photo 3.** View of weedy russian thistle debris piling up in the eastern portion/fence line.




Inspection Photos  
Location Name: Brown 32-6-03 1  
Location ID: 326188



**Photo 4.** Northern portion of the disturbance that is not needed for production/operations.  
This area needs to be interim reclaimed.



Inspection Photos  
Location Name: Brown 32-6-03 1  
Location ID: 326188



**Photo 5.** View of 2022 aerial imagery of the of the well disturbance. Area highlighted in red is past the 75 ft buffer of active equipment and is not needed for production/operations

API #: 067-07620