

# Final Reclamation and Stormwater Inspection

Date: 6/18/24

Operator: Axis Exploration LLC - 10646

Location ID: 320768

Inspection Document #: 713900702

Arapahoe County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: UPRC #21X-21  
Location ID: 320768



**Photo 1.** The photo was taken at the well location facing North. The photo illustrates the well and tank battery location are part of a land use change, the location is now a homestead.

**Photo 2.** The photo was taken at the well location facing East. The photo illustrates the mowed field to the East.

Inspection Photos  
Location Name: UPRC #21X-21  
Location ID: 320768



**Photo 3.** The photo was taken at the well location facing South. The photo illustrates the mowed field to the South.

**Photo 4.** The photo was taken at the well location facing West. Refer to the comment for photo 1.

Inspection Photos  
Location Name: UPRC #21X-21  
Location ID: 320768



**Photo 5.** The photo was taken at the approximate separator location facing North. The photo illustrates the land use change as well as the former access road is now in use as a driveway.

**Photo 6.** The photo was taken at the approximate separator location facing South. Refer to the comment for photo 1.