

Inspection Photos
Location Name: Elder Pad 6/20/2024
Location ID: 465636



Photo 1 Tank Battery Sign



Photo 2 Spills within tank battery secondary containment



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elder Pad 6/20/2024
Location ID: 465636



Photo 3 Spill at riser within tank battery secondary containment



Photo 4 Spills around Emission Control Devices



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elder Pad 6/20/2024
Location ID: 465636



Photo 5 Stock holding condensate/oil/water, No wildlife BMPs, Spills around stock tank



Photo 6 Secondary containment around chemical tank lacks wildlife BMPs



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elder Pad 6/20/2024
Location ID: 465636



Photo 7 Wildlife BMP in place around secondary containment at corrosion inhibitor tank



Photo 8 Wildlife BMP in place around secondary containment at chemical tank



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources