

Inspection Photos

API: 071-07241

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 6/21/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the access road There is erosion along the road which will need BMP's.



Inspection Photos



Photo 2. Facing toward the tanks near the location.



Inspection Photos



Photo 3. Facing southwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-07241 | Date: 6/21/2024