

Inspection Photos
Location Name: Antelope 41-17 PAD
Location ID: 423795



Photo 1 – 41-17 Wellhead



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Antelope 41-17 PAD
Location ID: 423795



Photo 3 – Wellheads



Photo 4 – Wellhead Sign

Inspection Photos
Location Name: Antelope 41-17 PAD
Location ID: 423795



Photo 5 – Separators – Tumbleweeds



Photo 6 – Signs

Inspection Photos
Location Name: Antelope 41-17 PAD
Location ID: 423795



Photo 7 – Tank Battery